

### **EPA**

U.S. EPA Region II 290 Broadway New York, NY 10007

# RST2 Technical Direction Document

TDD #; TO-0013-0039 Contract: EP-W-06-072

Core Response Team Year 4 (0013) Weston Solutions, Inc.

! = required field

TDD Name:	Raritan Bay Slag	! Period:	Option Period 1
! Purpose:	TDD Initiation		
! Priority:	High	! Start Date:	07/01/2009
Overtime:	Yes	! Completion Date:	12/31/2009
! Funding Category:	CERCLA\Removal	Invoice Unit:	
	and the second second		
! Project/Site Name:	Raritan Bay Slag	•	
Project Address:	Beach Area East of Route 36	Activity:	
County:	Middlesex	Work Area Code:	
City, State:	Laurence Harbor & Sayreville, NJ	Activity Code:	RV
Zip:		EMERGENCY CODE:	☐ KAT ☐ RIT
1 SSID:	1248 A705	FPN:	·
CERCLIS:	NJD980531545	Performance Based:	No .
Operable Unit:	· ·		
Authorized TDD C	Celling:	Cost	Fee LOE (Hours
1	Previous Action(s):	\$(	0.00 0.
	This Action:	\$(	0.00 200.
	New Total:	Si	0.00 200

#### **Specific Elements**

#### **Description of Work:**

Installation of security fencing and signage to prevent/limit public access to beach and waterfront contaminated with lead.

In accordance with the Response Section in the SOW, RST shall provide removal action support. The contractor shall perform the following activities:

- 1) Provide 1 person to support this effort. Prior to mobilization, contact the OSC to discuss site logistics and to determine if a meeting is required to discuss task assignments. Field work will be for approximately 10 days. Contact the Task Monitor to discuss date of mobilization;
- 2) Review ERRS prepared health and safety plan and provide comments to OSC as soon as parcticable;
- 3) Document on-site activities and maintain site log;
- 4) Photodocument site operations and provide photos to OSC within 5 days after completion of field event

No equipment is anticipated at this time.

### **Accounting and Appropriation Information**

						<u></u>				SFO:
Line	DCN	IFMS.	Budget/ FY	Appropriati	Budget Org	Program	Object	Site Project	Cost Org	Amount
				on.	Code	Element	Class		Code	
				Code						
	LIEO152		09	T	2AD0S	202DC4C	2505	A218??00	COOL	
	UEALSS	XXX	09	.1	ZADUS	302DCoC	2303	A218//UU	C001	\$0.00

Funding Summary:	Funding
Previous:	\$0.00
This Action:	\$0.00
Total:	\$0.00

Funding Category
CERCLA\Removal

Section

- Signed by Norman Vogelsang/R2/USEPA/US on 07/06/2009 06:54:56 AM, according to Jennifer Sy/sta

: Confortini Date: 07/06/2009

Project Officer Section - Signed by Norman Vogelsang/R2/USEPA/US on 07/06/2009 04:13:39 PM, according to

Project Officer: Norman Vogelsang Date: 07/06/2009

Contracting Officer Section - Signed by Anthony Tao/R2/USEPA/US on 07/07/2009 08:19:13 AM, according to

Contracting Officer: Anthony Tao Date: 07/07/2009

Contractor Section - Signed by Jennifer Sy/start6/rfw-start/us on 07/07/2009 01:11:45 PM, according t

Contractor Contact: Jennifer Sy Date: 07/07/2009

Au: Jager Oc: Brusan

## **REGION 2 RST 2**

### TDD FILE CHECKLIST

PROJECTNAME: RAR HAN BAY	1 5/49 TDD#:TO-	0013-0039
LEAD RST 2 MEMBER: JAGER		A *

REQUIRED (Y/N)	ITEM	DATE ENTERED
Y	TDD FORM	7-6-09
	TDD AMMENDMENTS	
Y	DRAFT AOC	
Y	FINAL AOC	
Y	H & S PLAN/WAIVER	·
	TRIP REPORT	
	LOG BOOK COPIES	
	SAMPLING PLAN	
,	ANALYTICAL DATA	
	SITE PHOTOGRAPHS/VIDEO	
	MAPS	
	OTHERS	
	OTHERS	
_	OTHERS	
	OTHERS	
	OTHERS	
	OTHERS	

Comments:	
Final file inspected by:	Date:



# SAFETY PLAN WAIVER FORM (TO BE INCLUDED IN TDD FILE)

TO: FILE
TDD#
PCS#
DESCRIPTION: Ravitan Bay Slag
DATE OF ISSUE: 07/07/09
RST MEMBER(S) ASSIGNED:
THE ABOVE REFERENCED TDD# DOES NOT REQUIRE A SAFETY PLAN DUE TO THE FOLLOWING REASON. (CHECK ALL THAT APPLY)
NO SITE VISIT WAS REQUIRED UNDER THE TASK DESCRIPTION OF THIS TDD BECAUSE:
FIRST RESPONSIVE COURSE
ADMINISTRATIVE TASK
TRAINING COURSE
CONFERENCE
COST ESTIMATE FOR THE SITE QA/QC REVIEW OF ANALYTICAL DATA
/ REFER TO HASP LOCATED ON TDD#
OTHER, SPECIFY TO follow ERRS HASP
ASSIGNED RST SIGNATUREDATE:
RST HSO APPROVAL DATE: 60/26/M